

ADDENDUM #2

DATE: February 7, 2024

TO: Prospective Proposers

RE: Addendum #2 Fire Alarm and Monitoring Services Tyler Junior College RFP #24-08

NOTICE TO PROPOSERS:

This Addendum forms a part of the Request for Proposal. Acknowledge receipt of this Addendum in the space provided on the Vendor Verification Form. Failure to do so may subject Proposer to disqualification.

BUILDING INSPECTION REPORTS ATTACHED that lists the number of devices per building and existing fire panels.

End



FIRE ALARM INSPECTION REPORT

	く正
College ting	mel/
5/15/2017 Tyler Junior College Baldwin Building Tyler	ary .
	A FICE
DATE COMPANY FACILITY ADDRESS CITY PHONE	Edwar

PASS Fall QTV TEST Q100 Pass Fall QTV Test 1000 Pass Trouble Sounder Trouble Light Pall Pall Trouble Light Pall Pall Pall Strobe Horms Pall Pauli Stations Duet Detectors Door Holders Sprinkler - Tamper	1000													
10 1 1 1 1 6 6 C	TEST	amp Test	Trouble Sounder	Prouble Light	Sattery Test	L.C. Power	trobe Horns	moke Detectors	vull Stations	Juct Detectors	boor Holders	prinkler - Flow	prinkler - Tamper	
	QTY A		1				4	2	5	7		S	S	「日時日日本の行いた

LICENSE Number Fbé Alam



FIRE ALARM INSPECTION REPORT

5/15/2017 Tyler Junior College Center Of Earth & Sciene	Tyler
DATE COMPANY FACILITY ADDESS	CITY

2	TEST	Lamp Test	Trouble Sounder	Trouble Light	Battery Test	A.C. Power	Strobe Horns	Smoke Detectors	Pull Stations	Duct Detectors	Door Holders	Sprinkler - Flow	Sprinkler - Tamper	Consideration Tons
0000-000	QTY		I State of the second s			V AN AN AN AN	38	X	5	a	9	21	5	
9	FAIL			sense de senses										
	PASS	1	1	1	1	V	1	1		I		T	-	

The Fire Alarm was found to be in good working order. 5/15/2018 Next Inspection Due:

License /



FIRE ALARM INSPECTION REPORT

5/15/2017	IY Tyler Junior College	Field House	S	Tyler	
DATE	COMPANY	FACILITY	ADDRESS	CITY	PHONE

Fire Lite Alarms mini Scan # 424 4 2012

TEST	Lamp Test	Trouble Sounder	Trouble Light	Battery Test	A.C. Power	Strobe Horns	Smoke Detectors	Pull Stations	Duct Detectors	Door Holders	Sprinkler - Flow	Sprinkler - Tamper	Sensitivity Test
QTY			※11日 出版			M	2	5			All and a second s		
FAIL						and the second							
PASS	1		1		/	2	1	1	7				

The Fire Alarm was found to be in good working order. Next Inspection Due: 5/15/2018

٦

Licens



FIRE ALARM INSPECTION REPORT

5/15/2017	COMPANY Tyler Jun	FACILITY Gencov	ADDRESS	Tyler	PHONE
-	Tyler Junior College				

EST 10 5000 Simplex 4100 Panel

PASS	FAIL	0TY	TEST
>			Lamp Test
2			Trouble Sounder
>		and the state of the	Trouble Light
1			Baltery Test
2			A.C. Power
2		53	Strobe Horns
2		32	Smoke Detectors
5		12	Pull Stations
5		S	Duct Detectors
			Door Holders
			Sprinkler - Flow
			Sprinkler - Tamper
		U State	Sensitivity Test

The Fire Alarm was found to be in good working order. Next Inspection Due: 5/15/2018

Fire Althm Lices

Licelse Number



FIRE ALARM INSPECTION REPORT

DATE	5/15/2017
COMPANY	Tyler Junior College
FACILITY	Jenkins Hall
ADDRESS	
CITY	Tyler
PHONE	

TEST	Lamp Test	Trouble Sounder	Trouble Light	Battery Test	A.C. Power	Strobe Horns	Smoke Detectors	Pull Stations	Duct Detectors	Door Holders	Sprinkler - Flow	Sprinkler - Tamper	Consilinity, Tost
VIO		100 100 100 100 100 100 100 100 100 100				20	4				3	3	いたいたいというです。
S FAIL													
PASS	1	2	5	5	2	>	5	5			>	1	

The Fire Alarm was found to be in good working order. 5/15/2018 Next Inspection Due:

License Numl



FIRE ALARM INSPECTION REPORT

Ë								
ary	Panel					Tyler Junior College	017	
G	, j		Tyler		OHPE	Tyler.	5/15/2017	
FAIL	JOCHIK			s		٢		
DACS	Ho	PHONE	CITY	ADDRESS	FACILITY	COMPANY	DATE	

|--|

The Fire Alarm was found to be in good working order. Next Inspection Due: 5752018

0

License Nu



FIRE ALARM INSPECTION REPORT

					3127.6NC	Silant Kicht model SKIS20812									
					-1.1-	SKIS	ST		L			- 140 - 14 - 14 - 14		2	
	ollege	nter				model	TEST	Lamp Test	Trouble Sounder	Trouble Light	Battery Test	A.C. Power	Strobe Horns	Smoke Detectors	
5/15/2017	Tyler Junior College	Pirtle Tech Center		Tyler		Kight -	arv	のなど、あたけ、					35	7	
	NY	7	SS			lent	FAIL		11-						
DATE	COMPANY	FACILITY	ADDRESS	CITY	PHONE	N	PASS			-	1	1		1	

The Fire Alarm was found to be in good working order. Next Inspection Due: 5/15/2018

Sprinkler - Tamper

Sensitivity Test

Sprinkler - Flow

Duct Detectors Door Holders

NN

Pull Stations

10

Alarm.C First

License Numb

Page 8 of 33



FIRE ALARM INSPECTION REPORT

COMPANY Tyler Junior College COMPANY Tyler Junior College FACILITY Pirtle Tech Phase 1 ADDRESS Truns	Tulor
---	-------

$\tilde{\lambda}$
$\Delta c_{\rm e}$
1.1
1
1
16

wi Licens



FIRE ALARM INSPECTION REPORT

DATE

		Silent Kight model SK/5208/3 ZONE	-													
llege		model SK	TEST	Lamp Test	Trouble Sounder	Trouble Light	Battery Test	A.C. Power	Strobe Horns	Smoke Detectors	Pull Stations	Duct Detectors	Door Holders	Sprinkler - Flow	Sprinkler - Tamper	Sensitivity Test
5/15/2017 Tyler Junior College Potter Hall	Tyler	K:94+	ary	T Star Star			B CONSTRUCTION B	V STATES	38 5	4	9	7		S	S	S Harris State
>. 0		tus	FAIL					and a strate for the state								1
DATE COMPANY FACILITY	CITY	Si/	PASS	-	~		1	1		5	2					

The Fire Alarm was found to be in good working order. Next Inspection Due: 5/15/2018 Sensitivity Test Due:

Must lee-

5853MJ

License Number



FIRE ALARM INSPECTION REPORT

DATE	5/15/2017
COMPANY	Tyler Junior College
FACILITY	Rogers School of Nursing
ADDRESS	
CITY	Tyler
PHONE	

	TEST	amp Test	Trouble Sounder	Trouble Light	Battery Test	A.C. Power	Strobe Horns	Smoke Detectors	Pull Stations	Duct Detectors	Door Holders	Sprinkler - Flow	Sprinkler - Tamper	Sensitivity Test
× 4100	QTY		が設めた。	T HAN WE WARE TO	「新学生生化派」		325 5	89	2	13		S	7	
Simplex	FAIL													
Sit	PASS		5	5	1	7	7	1	1		1 ¥	1	1	

C-5954 Licenservumb



FIRE ALARM INSPECTION REPORT

DATE COMPANY	5/15/2017 Tyler Junior College
ADDRESS	Kogers Student
CITY	Tyler
DHONE	

Simplex 4100 Simol × 4002 -

Auro Battery Test	Trouble Sounder	OTY TEST	
Strobe Horns Strobe Horns U Smoke Detectors	Strobe Horns Strobe Horns (1) Strobe Horns (1) Smoke Detector	 Trouble Sounds Trouble Light Trouble Light Trouble Light A.C. Power Strobe Horns Strobe Horns Smoke Detector 	Stroke Lamp Land Strouble Light Markey Rest Stroke Horns Stroke Detecto
and the second s	A Battery Test	Trouble Sounder Trouble Light	Addition of the second se second second sec

Murth-U. Free Alarmi Licensee TMU 5582 vsee Munuber



FIRE ALARM INSPECTION REPORT

DATE	5/15/2017
COMPANY	Tyler Junior College
FACILITY	Satellite Physical Plant
ADDRESS	
CITY	Tyler
PHONE	
2	

ST		4					5				2	per	
TEST	Lamp Test	Trouble Sounder	Trouble Light	Battery Test	A.C. Power	Strobe Horns	Smoke Detectors	Pull Starions	Duct Detectors	Door Holders	Sprinkler - Flow	Sprinkler - Tamper	Sensitivity Test
ary						9	\$	e					100000 - 2000 - 20000
FAIL													1
PASS	>	>	>	>	>	7	1	>					+

The Fire Alarm was found to be in good working order. 5/15/2018 Next Inspection Due: Sensitivity Test Due:

FAL 5782 License Number

Purt he



FIRE ALARM INSPECTION REPORT

5/15/2017	Tyler Junior College	Tennis Complex		Tyler		
DATE	COMPANY	FACILITY	ADDRESS	CITY	PHONE	

4100			Hand Street											
Simplex	TEST	Lamp Test	Trouble Sounder	Trouble Light	Battery Test	A.C. Power	Strobe Horns	Smoke Detectors	Pull Stations	Duct Detectors	Door Holders	Sprinkler - Flow	Sprinkler - Tamper	Sensitivity Test
	QTY						30	8					-1	
ES+ 2	FAIL													
	PASS		1	/	/	1	1	2						

The Fire Alarm was found to be in good working order. Next inspection Due: 5/52018

Licens



FIRE ALARM INSPECTION REPORT

5/15/2017	Tyler Junior College	Vaughn Conservatory		Tyler		
DATE	COMPANY	FACILITY	4DDRESS	CITY	PHONE	

00	TEST	Lamp Test	Trouble Sounder	Trouble Light	Battery Test	A.C. Power	Strobe Horns	Smoke Detectors	Pull Stations	Duct Detectors	Door Holders	Sprinkler - Flow	Sprinkler - Tamper	Sensitivity Test
Simplex 4100	ary						6	9	9	4	7	S	S	
oimp	FAIL													
^	PASS	1	2	7	21	2	2	5	7				1	

The Fire Alarm was found to be in good working order. 5/15/2018 Next Inspection Due:

FAL-2173792 License Number



FIRE ALARM INSPECTION REPORT

DATE	2/15/017	
22.14	IINTICIIC	
COMPANY	Tyler Junior College	
FACILITY	Wagstaff Gym	
ADDRESS		
CITY	Tyler	
PHONE		
FS7 2	with dulin	

4100

lex		1				_	1				1			1
Simplex	ST					and the second state of th		10					cer	Name of Address of Stationary Party and Stationary Party
Andio	TEST	Lamp Test	Trouble Sounder	Trouble Light	Battery Test	A.C. Power	Strohe Horns	Smoke Detectors	Pull Stations	Duct Detectors	Door Holders	Sprinkler - Flow	Sprinkler - Tamper	Sensitivity Test
with Audio	QTY						65	£	12	6				No. of the second s
7 2	FAIL													1
ES!	PASS	2	2	2	7	2	7	7	7	2				t

The Fire Alarm was found to be in good working order. Next inspection Due: 5/15/2018 Sensitivity Test Due: Fire Alarm Licensee HUGO License Number



FIRE ALARM INSPECTION REPORT

5/15/2017 Tyler Junior College White ADM	Tyler
DATE COMPANY FACILITY	CITY

0	
5	77
XX	0
10m	FAIL
S	PASS

							10.44				1990 - 1990 - 1990 - 1990 - 1990 - 1990 - 1990 - 1990 - 1990 - 1990 - 1990 - 1990 - 1990 - 1990 - 1990 - 1990 -		
TEST	Lamp Test	Trouble Sounder	Trouble Light	Battery Test	A.C. Power	Strobe Horns	Smoke Detectors	Pull Stations	Duct Detectors	Door Holders	Sprinkler - Flow	Sprinkler - Tamper	
arv						5/ 15	19 5	18	13	7	4 5	2 5	「「「「「「「」」」」」」」」」」」」」」」」」」」」」」」」」」」」」」」
FAIL										j			
PASS	1	1	1	1	Y	1	Y	2	1	r	5	7	

THE Sig 2

Mutt / Lu



FIRE ALARM INSPECTION REPORT

5/15/2017 Tyler Junior College Wise Auditorium	ESS Tyler
DATE	ADDRESS
COMPANY	CITY
FACILITY	PHONE

					1		1							-
ranel	TEST	Lamp Test	Trouble Sounder	Trouble Light	Battery Test	A.C. Power	Strobe Horns	Smoke Detectors	Pull Stations	Duct Detectors	Door Holders	Sprinkler - Flow	Sprinkler - Tamper	Sensitivity Tver
1	ary			1			22	15	12	2		2	S	国行の法律
メートノンショ	FAIL													
	PASS	1	4	1	1	1	1	1	5	7		1		

The Fire Alarm was found to be in good working order. Next Inspection Due: 5/15/2018

License Number

Fe Alarm Lice

Ľ.

Page 18 of 33



FIRE ALARM INSPECTION REPORT

5/15/2017		Wise Cultural Aris		Tyler	
DATE	COMPANY	FACILITY	ADDRESS	CITY	PHONE

FAIL OTY Land

LLocuse Num



FIRE ALARM INSPECTION REPORT

5/15/2017	Tyler Junior College	Bateman Hall		Tyler		St. 01 11. 20
DATE	COMPANY	FACILITY	ADDRESS		PHONE	2

0	
0	
-	
J	
X	(
-	
9	5
3	
	1
5	
- I	001
	Ì

PASS	FAIL	ary	TEST
			Lamp Test
~			Trouble Sounder
			Trouble Light
1			Battery Test
1			A.C. Power
1		古	Strobe Horns
1		16	Smoke Detectors
		2	Pull Stations
1			Duct Detectors
		an allow an allow an allow and	Door Holders
	1		Sprinkler - Flow
			Sprinkler - Tamper
			Sensitivity Test

FAL-5 agy License Number Alarm L E



FIRE ALARM INSPECTION REPORT

2/15/2017	Tyler Junior College	Claridge Hall		Tyler	
DATE	COMPANY	FACILITY	ADDRESS	CITY	PHONE

X	ł
2	ŀ
e	ŀ
्र	
5	

And Composition Comp Test And Complexity Trouble Sounder And Complexity Trouble Sounder And Complexity Trouble Sounder And Complexity Battery Test And Complexity Strobe Horus And Complexity Strobe Horus And Complexity Strobe Horus And Complexity Strobe Horus And Complexity Duet Detectors And Complexity Strobe Horus And Complexity Strobe Horus And Complexity Strobe Horus And Complexity Strobe Horus And Complexity Strobe Horus	PASS	FAIL	QTY	TEST
A Trouble Sounder Reserve Trouble Light Reserve Ballery Test Reserve Strobe Horns Sounder Strobe Horns Source Duet Detectors Sprinkler - Flow Sorrinkler - Tamper				Lamp Test
Sector Trouble Light Exact Battery Test Exact Battery Test Exact Strobe Horns Sinde Detectors Duct Detectors Sprinkler - Flow Strinkler - Flow	1			Trouble Sounder
A Battery Test A C. Power A C. Power A Strobe Horns B Strobe Horns B Puil Stations Duct Detectors Duct Detectors Sprinkler - Flow Sprinkler - Flow	1			Trouble Light
C Power C Pull Stations C Pull Stations Duct Detectors Door Holders Sprinkler - Flow	1			Battery Test
Strobe Horns S7 Strobe Horns S7 Smoke Detectors Pull Stations Duct Detectors Sprinkler - Flow Sprinkler - Tamper	1			A.C. Power
87 Smoke Detectors 8 Puil Stations Duct Detectors Sprinkler - Flow Sprinkler - Tamper	>		93	Strobe Horns
K Puil Stations Duct Detectors Door Holders Sprinkler - Flow	2		87	Smoke Detectors
Duct Detectors Door Holders Sprinkler - Flow Sorinkler - Tamper	2		8	Pull Stations
Door Holders Sprinkler - Filow Sorinkler - Tamber				Duct Detectors
Sprinkler - Flow Sorinkler - Tamper				Door Holders
Sprinkler - Tamper				Sprinkler - Flow
				Sprinkler - Tamper



FIRE ALARM INSPECTION REPORT

5/15/2017	Tyler Junior College	Residence Hall	Crossrouds	Tyler	
DATE	COMPANY	FACILITY	ADDRESS	CITY	PHONE

DASS	FAIL	0TY	TEST
1			Lamp Test
-			Trouble Sounder
-			Trouble Light
+			Ballery Test
1			A.C. Power
-		220	Strobe Horns
L		000	Smoke Detectors
		13	Pull Stations
t			Duct Detectors
1			Door Holders
1		2	Sprinkler - Flow
1		5	Sprinkler - Tamper
Г			Sensitivity Test

License Number larm Lice



FIRE ALARM INSPECTION REPORT

\$/15/2017	COMPANY Tyler Junior College	FACILITY Holley Hall	ADDRESS CITY Tyler	
	or College	11		

-	
3	
0	
2	
	1
X	
<u> </u>	
5	
Ч	-
8	
2	1
0	
٧Y	
	1

		225
PASS FAIL	QTY	TEST
1		Lamp Test
1		Trouble Sounder
-		Trouble Light
		Battery Test
X		A.C. Power
1	55	Strobe Horns
7	29	Smoke Detectors
)	4	Pull Stations
7	_	Duct Detectors
/		Door Holders
1		Sprinkler - Flow
/		Sprinkler - Tamper
>		Sensitivity Test

FUE Alargh Licensee

License Ni



FIRE ALARM INSPECTION REPORT

5/15/2017	Tyler Junior College	Hudnall Hall		Tyler	
DATE	COMPANY	FACILITY	ADDRESS	CITY	PHONE

			2	2
			,	-
	١	U	٢	3
E				
1				
1				

Fair Or



FIRE ALARM INSPECTION REPORT

5/15/2017	Tyler Junior College	Lewis Hall		Tyler		L'en Durel
DATE	COMPANY	FACILITY	ADDRESS	CITY	PHONE	11201.1

							1	second strength		1		1		NIII N
61	TEST	Lamp Test	Trouble Sounder	Trouble Light	Battery Test	A.C. Power	Sirobe Horns	Smoke Detectors	Pull Stations	Duct Detectors	Door Holders	Sprinkler - Flow	Sprinkler - Tamper	Sensitivity Test
i jumer	Го	の中にの対応の言					<u></u>	~	7				And a second sec	
HOCK, KI	FAIL					-							a submitted of the state of the	
HC	SSVd	5	1	5		1	1	~	2					

The Fire Alarm was found to be in good working order. Next Inspection Due: 5:152018 PH-L-JITZM2 License Number

Fire Alarm Gensee



FIRE ALARM INSPECTION REPORT

5/15/2017	Tyler Junior College	Ornelas A		Tyler		
DATE	COMPANY	FACILITY	ADDRESS	CITY	PHONE	

simplex panel

PASS FAIL	QTY V TEST
1	Test Lamp Test
1	Trouble Sounder
//	A Date of Trouble Light
1	and the Battery Test
	A.C. Power
X	147 Strobe Horns
1	P. 7. S. Smoke Detectors
1	7 7 Pull Stations
	3 Duct Detectors
-	Door Holders
	5 Sprinkler - Flow
1	7 Sprinkler - Tamper
	Concitivity Test



FIRE ALARM INSPECTION REPORT

	llege					u
5/15/2017	Tyler Junior College	Ornelas B		Tyler		1 6
DATE	COMPANY	FACILITY	ADDRESS	CITY	PHONE	< · · · · >

00		1		a strength and					ł					
E FP/1000	TEST	Lamp Test	Trouble Sounder	Trouble Light	Battery Test	A.C. Power	Strobe Horns	Smoke Detectors	Pull Stations	Duct Detectors	Door Holders	Sprinkler - Flow	Sprinkler – Tamper	Sensitivity Test
Knight	arv						142	225	13				~	
Silvert	FAIL													
511	PASS		0	1	1		1	1	2	2		2		3

License Num Alarn



FIRE ALARM INSPECTION REPORT

5/15/2017				Tyler	
DATE	COMPANY	FACILITY	ADDRESS	CITY	PHONE

													and an and a second sec
TEST	Lamp Test	Trouble Sounder	Trouble Light	Battery Test	A.C. Power	Strobe Horns	Smoke Detectors	Pull Stations	Duct Detectors	Door Holders	Sprinkler - Flow	Sprinkler - Tamper	
277						69	45	+		7	S	S	The same of the second s
FAIL													
PASS	7	7	1	1	1	Z	1	N					A COLUMN TO A COLUMNT TO A COL



FIRE ALARM INSPECTION REPORT

5/15/2017	Tyler Junior College	Vaughn Hall		Tyler		· · · · · · · · · · · · · · · · · · ·
DATE	COMPANY	ACILITY	ADDRESS	SITY	PHONE	

TEST	Lamp Test	Trouble Sounder	Trouble Light	Battery Test	A.C. Power	Strobe Horns	Smoke Detectors	Pull Stations	Duct Detectors	Door Holders	Sprinkler - Flow	Sprinkler - Tamper	
QTY	Same and		語の中の言語の			48	32 5	J	7	7	S	S	いたいというというか
FAIL		Marine and Andrew State											
PASS	1		1	1	1		1	7		1		1	

The Fire Alarm was found to be in good working order. Next Inspection Due: 5/152018

1

License Numb



FIRE ALARM INSPECTION REPORT

5/15/2017 Tyler Junior College Wesley Hall	Tyler
DATE COMPANY FACILITY ADDRESS	SITY

ז	
ex	
API.	EAN .
Siv	
	pace

				Ann 19 York Addin - Anna - Harrison In Stranger	a ferritream year cases			first on their succession of	And the same surrough the same					
00	TEST	Lamp Test	Trouble Sounder	Trouble Light	Battery Test	A.C. Power	Strobe Horns	Smoke Detectors	Pull Stations	Duct Detectors	Door Holders	Sprinkler - Flow	Sprinkler - Tamper	Sensitivity Test
LX HIDD	QTY					の世界がある	14 15	28 5	4	7	9	S.	S	S
Simplex	FAIL		a serie a versión a verse se								-			294
V	PASS))`))	5	1	2			a salah ang sang sang salah	TABLE AND A TABLE	-

The Fire Alarm was found to be in good working order. 5/15/2018 Next Inspection Due: FAL-2172792 License Number

Fire Alarm Deense



FIRE ALARM INSPECTION REPORT

5/15/2017	Tyler Junior College	Energy Building		Tyler		
DATE	COMPANY	FACILITY	ADDRESS	CITY	PHONE	•

<		(amo)
2	2	
x	0	文書書
10	FAIL	
S	PASS	>

TEST	Lamp Test	Trouble Sounder	Trouble Light	Battery Test	A.C. Power	Strobe Horns	Smoke Detectors	Pull Stations	Duct Detectors	Door Holders	Sprinkler - Flow	Sprinkler - Tamper	Sensitivity Test
QTY	Lam	Troi	Troi	Batt	AC.	57 Stroi	37 Smo	S Pull	6 Duci	D00)	V Spri	4 Sprin	Sent.
FAIL	120			19902	2,235								
PASS	2	>	2	24	2	7	1	7	7		1	2	

PAL- 2(72792 License Number Fire Alg

Page 31 of 33



FIRE ALARM INSPECTION REPORT

College			TES	Lamp Test	Trouble Sounder	Trouble Light	Battery Test
5/15/2017 Tyler Junior College RTDC	Tyler	Knight	ary				
5.9		Silcht	FAIL				
DATE COMPANY FACILITY ADDRESS	CITY	S.	PASS	-/i-	2	2	2

knight	Y TEST	Lamp Test	Trouble Sounder	Trouble Light	Battery Test	A.C. Power	Strobe Horns	Smoke Detectors	Pull Stations	Duct Detectors	Door Holders	Sprinkler - Flow	- Sprinkler - Tamper	Concision Sensitivity Test
orlent Kni	FAIL Q1									>	2			
ñ	PASS	1/i	1	2	2	2	2		2		>	2	2	and the second se

The Fire Alarm was found to be in good working order. Next Inspection Due: 5452018

Firestiarm Licensee

FR- - 417292

Page 32 of 33



FIRE ALARM INSPECTION REPORT

\$/15/2017	Tyler Junior College	Skill Center		Tyler		
DATE	COMPANY	FACILITY	ADDRESS	CITY	PHONE	F27

	F	
	S	
Į	W	
)		

TEST	Lamp Test	Trouble Sounder	Trouble Light	Battery Test	A.C. Power	Strobe Horns	Smoke Detectors	Pull Stations	Duct Detectors	Door Holders	Sprinkler - Flow	Sprinkler - Tamper	Sensitivity Test
QTY			1 (a . 11 . 1 . 1 . 1 . 1			20 40	18	20 4			M	5	
FAIL													
PASS	2	5	1	2	2	/	1	2))	

FOCKTIN-292 FUE Alarm Lice